

bottom of trim and/or corner on to bottom of enclosure and fasten

**⊚** 

 ${\color{red} \overline{\mathcal{O}}}$  If an access panel is used, join access panel to enclosure panel by

joiner (See Detail 'A'). Panel Joiners are made as 2 'L' shaped halves.

a joiner strip and an additional pedestal base. (not shown) For trims and corners, slide down over enclosure and snap

**4**0 Install heating element onto element supports, ensure tubing rest in cradle. <u>ω</u>

on top of pedestal base.

For 2 tier elements, mount and fasten additional tier brackets

cradle into the hole in the pedestal top.

**(N)** 

Fasten tops of pedestal base. Install cradles by placing cradle on

pedestal base tops and insert the plastic fastener through the slot in the

Slide enclosure panel into pedestal base and screw bottom of panel on to the base.

Note: all fasteners to be provided by the installing contractor.