



- As shown fasten 1" angle to floor 5 3/16" from wall.
- 2 Mount BKTEO brackets so that element center is 6" above floor.
- (3) For 2 tier elements, mount and fasten BKTEO brackets 6" center to center.
- 4 Install cradles onto brackets by placing cradle on bracket and insert the plastic fastener through the slot in the cradle into the hole in the bracket.
- (5) Install heating element on to BKTEO brackets, ensure tubing rests on cradle.
- 6 Place top of enclosure panel on to hanger strip and fasten panel to angle by #10 screws.

- (7) For 2 or more side by side enclosure panels, join by a panel joiner.
- 8 If an access panel is used, join access panel to enclosure panel by a joiner strip. (not shown)
- 9 Hook trim strip into hanger strip, swing trim down and fasten it to enclosure panel by #10 screws. For corners (9a), fasten at top and bottom by #10 screws.
- (10)If an access door is required, locate it on enclosure panel, cut out a 5 1/2" square opening and drill four 1/4" diameter holes on corners of 6 1/2"square. Mount and fasten access door assembly.